

CORRES. CONTROL
INCOMING LTR NO.

00010RF05

DUE DATE

ACTION

[illegible]

COR. CONTROL	X	X
ADMIN. RECORD	X	X
PATS/130		

Reviewed for Addressee
Corres. Control RFP

Date 1-12-05 By [Signature]

Ref. Ltr. #

DOE ORDER #

5402.1

RECEIVED

2005 JAN 12 P 3: 54



CORRESPONDENCE
CONTROL

⁵Department of Energy

ROCKY FLATS PROJECT OFFICE
10808 HIGHWAY 93, UNIT A
GOLDEN, COLORADO 80403-8200

JAN 03 2005

04-DOE-00988


Mr. Steven H. Gunderson
Rocky Flats Cleanup Agreement Project Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

Dear Mr. Gunderson:

Please find enclosed a completed Rocky Flats Cleanup Agreement Type 1 Building Disposition Closeout Report provided for your information for Building 664 – Waste storage, preparation, staging and shipping facility, and T664A – general office trailer.

Questions may be directed to Gary Morgan, Rocky Flats Project Office, at (303) 966-6003.


Sincerely,


Joseph A. Legare, Director
RFPO Project Management

Enclosure

cc w/o Encl.:
S. Nesta, K-II RISS Env
C. Freiboth, K-H RISS D&D
K. Wiemelt, K-H RISS D&D
M. Aguilar, USEPA
D. Abelson, RFCLOG

cc w/ Encl:
G. Morgan, RFPM, RFPO
D. McCranie, HQCPM, RFPO
Administrative Record



ADMIN RECORD

IA-A-002518

Section A. Facility Data	
Facility No.	Building 664 and T664A
Facility Descriptor:	B664 - Waste Storage, preparation, staging, and shipping facility T664A - General office trailer
Project:	RJSS
Date of Demolition:	T664A - 10/28/04 and B664 - 10/30/04
Additional Information:	
<i>(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)</i>	
Section B. Final Characterization Data	
Reconnaissance Level Characterization Report <i>(concurrence received)</i>	Reconnaissance Level Characterization Report (RLCR) for Building 664 and T664A - Concurrence from Steven Gunderson to Joe Legare on October 27, 2004
In-process Characterization	N/A
Pre-Demolition Survey Report <i>(approval received)</i>	RLC functioned as PDS
Post-Demolition Survey Report <i>(as necessary)</i>	N/A
Section C. Waste Data <i>(complete categories as appropriate)</i>	
Sanitary Disposal	
Disposal Site:	BFI Foothills Landfill, Golden CO
Waste Volume (yd ³):	7330
Waste Weight (tons):	3997.3
Additional Information:	Building debris
Hazardous Disposal	
Disposal Site:	Kettleman Hills Facility, Kettleman City, CA
Waste Volume (yd ³):	Approximately 60 cubic yards (46,544 lbs)
Additional Information:	Three rollofs of lead shielding (D008) from a High Contamination Area that could not be recycled, and one drum of crushed light bulbs (D009).
TSCA Waste Disposal	
Disposal Site:	N/A
Waste Volume (m ³):	N/A
Additional Information:	
Asbestos Waste Disposal	
Disposal Site:	N/A
Waste Volume (m ³):	N/A
Additional Information:	
Low-Level Waste Disposal	
Disposal Site:	N/A
Waste Volume (m ³):	N/A
Additional Information:	
Low-Level Mixed Waste Disposal	
Disposal Site:	N/A
Waste Volume (m ³):	N/A
Additional Information:	
Recycled Material	
Recycle Facility:	N/A
Waste Volume (m ³):	N/A
Additional Information:	
Property Disposition	
Receiver Locations <i>(major items only)</i> :	N/A
Volume (m ³):	
Weight (tons):	
Additional Information:	

Section D. Approvals

Kaiser-Hill Project Manager

Name/Signature

Date

Additional Facility Information

Building 664 was an approximately 18,700 square foot building constructed in 1972. The structure was a pre-fabricated metal building built on a concrete foundation. The exterior walls were constructed of insulated metal panels attached to a steel frame. The roof was constructed of metal decking with built-up roofing.


Building 664 had the following utilities: electrical, plant water, plant sanitary, plant steam, and fire protection was provided by an overhead sprinkler system and wall mounted fire extinguishers.

Building 664 contained RCRA Container Storage Unit 20, which was closed in accordance with the Closure Description Document submitted August 3, 2004. CDPHE acceptance of the closure summary report was received on November 8, 2004.

Trailer T664A was a 4,392 square foot general office trailer acquired in 1991. This trailer had corrugated metal siding with corrugated metal skirting. The entrances had wooden stairs leading to a wooded enclosure. The interiors were primarily a cubical layout, but had several hard-walled offices, conference rooms, and rest rooms. Interior walls were wallboard, the ceiling was a drop ceiling with acoustical tiles and recessed lights. The floors were primarily covered with carpet except in the bathrooms, which were covered with vinyl tile.

Trailer T664A had the following utilities: electrical, plant water, plant sanitary, and fire protection was provided by an overhead sprinkler system and wall mounted fire extinguishers.

The entire B664 and T664A structures were removed during D&D activities, and sent offsite for disposal. The utilities were disconnected and removed to at least three feet below final grade as indicated on the attached map. There are no remaining structural components, utility lines, or parts of the foundation. The buildings are not in an IHSS or PAC therefore no soil sampling is required.



Rocky Plate Environmental Technology Site

664 and T664 Location Map

Map Features

- ☐ Buildings Remaining
- ☐ D8D Facility
- ☒ Paved Roads
- ☒ Dirt Roads
- ☒ Lakes
- ☒ Railroad Removed
- ☒ Railroad Remaining
- ☒ Fence Removed
- ☒ Fence Remaining
- ☒ Streams

N

1:340
1 inch equals 25 feet
Rocky Plate Continuous Production
Caliente Control Zone (CZP)
Datum: NAD83


U.S. Department of Energy
Rocky Plate Environmental Technology Site

Prepared by
CH2M HILL

Project No.
1001
Rocky Plate

U.S. Department of Energy
Rocky Plate Environmental Technology Site
Location Map

5/5



KEY:
= STEAM & CONDENSATE
= SANITARY SEWER
= WATER SERVICE
= ELECTRICAL SERVICE